

E 14

E - 17

Carburetor

The diagram shows an exploded view of a carburetor assembly. Various components are labeled with numbers from 1 to 51. Key parts include the base (31), fuel tubes (29, 34), jets (19, 20), and various screws and washers. The diagram is oriented with 'FR.' (Front) at the bottom and 'KCR3-E1700A' at the top right.

KCR3-E1700A

Service item	F.R.T.	Ref. Part No.	Description	Reqd. QTY		Serial No.	Area code
				WT/MC	S X		
		29	16179-KE5-004	CLIP, TUBE.....	2	2	
		30	16180-KY6-004	T-JOINT.....	1	-	
			16958-MB0-000	JOINT, FUEL TUBE.....	-	1	
		31	16188-KBV-000	BASE, AIR CLEANER.....	1	1	
		32	16197-KCR-000	TUBE.....	1	1	
		33	16198-KCR-000	TUBE, FUEL.....	1	1	
		34	16199-KCR-000	TUBE.....	1	1	
		35	16199-KY6-004	TUBE.....	1	1	
		36	91410-KCR-000	CLIP, 2X70.....	1	1	
		37	91410-MN1-671	CLIP, 2X70.....	1	1	
		38	93500-04008-1A	SCREW, PAN, 4X8.....	4	4	
		39	93500-04010-1A	SCREW, PAN, 4X10.....	8	8	
		40	93892-04008-10	SCREW-WASHER, 4X8.....	1	1	
		41	93892-04016-10	SCREW-WASHER, 4X16.....	6	6	
		42	93892-05010-10	SCREW-WASHER, 5X10.....	1	1	
		43	93892-05014-10	SCREW-WASHER, 5X14.....	1	1	
		44	95001-75040-40	TUBE, FUEL, 7.5X40 (95001-75001-60M)	1	1	
		45	95002-02120	CLIP, TUBE (B12).....	5	-	
			95002-02129	CLIP, TUBE (B12).....	-	5	
		46	99101-GHB-1100	JET, MAIN, #110.....	2	-	
			99101-393-1100	JET, MAIN, #110.....	-	2	
		47	99103-437-0350	JET, SLOW, #35.....	2	-	
			99103-MT2-0350	JET, SLOW, #38.....	-	2	
			1999.03.10	E			E14

2

53